

**APPENDIX to the 2020 Annual Report for the Program Comment for
Department of the Army Inter-War Era Historic Housing, Associated Buildings and Structures, and Landscape Features (1919–1940)**

Lifecycle Data Tracking for Imitative Substitute Building Materials and In-kind Building Materials

This information is provided in accordance with the requirements of the Program Comment for Department of the Army Inter-War Era Historic Housing, Associated Buildings and Structures, and Landscape Features (1919–1940) (Program Comment) issued by the Advisory Council on Historic Preservation on 4 Sep 2020. These data represent Army tracking of lifecycle data for in-kind and imitative substitute building materials used on 361 Inter-War Era housing units present on two Army installations, one in the mid-Atlantic (in-kind wood replacement windows, synthetic (faux) slate roofing, and fiber cement siding), and the other in the Southeast (vinyl replacement windows, PVC window trim). The Tabs on this spreadsheet correspond to the building materials type and contain the data points being tracked for each building material type. The data will be collected at the individual housing unit level and reported annually from 2020 to 2025, and will then be collected and reported at five-year intervals, in 2030, 2035, 2040, 2045, 2050, and 2055. These data are presented to the ACHP as part of the 2020 Annual Report and represent the initial submission of these data in satisfaction of the Program Comment.

361 total Inter-War Era historic housing units are being tracked. The following in-kind building material and imitative substitute building material types used on the 361 Inter-war Era historic housing units are tracked in the corresponding Tabs, in accordance with the Program Comment:

- Tab 1. Windows, vinyl replacement - 202 housing units
- Tab 2. PVC window trim - 202 housing units
- Tab 3. Windows, in-kind wood replacement - 83 housing units
- Tab 4. Synthetic slate roofing - 76 housing units
- Tab 5. Fiber cement siding - 76 housing units

The following data points are presented in each TAB for each in-kind building material and imitative substitute building material type. Data Columns E and F will be populated as materials are replaced:

- A. Housing Unit Number
- B. Date of Housing Unit Construction
- C. Year New Material Installed (initial installation)
- D. Year New Material Replaced - this information will be filled out as the material is replaced
- E. Total Lifecycle of New Material - lifecycle will be calculated at the time of replacement of new material (number of years)
- F. Lead Paint Hazard Removed? (Y/N/ Not Applicable)
- G. Warranty (y/n)
- H. Warranty (# years)
- I. Warranty Terms of Replacement - includes information regarding terms of replacement (if any)

To ensure accuracy, the Army will change, amend, update, or withdraw and correct these data at any time, as needed.

Tab 1. Windows Vinyl Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|--|
| 1 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 2 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 3 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 4 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 5 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 6 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 7 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 8 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 9 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 10 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 11 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 12 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 13 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 14 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 15 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 16 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 17 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 18 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 19 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 20 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 21 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 22 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 23 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 24 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 25 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 26 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 27 | 1934 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 28 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 29 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 30 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 31 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 32 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 33 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 34 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 35 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 36 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 37 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 38 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 39 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 40 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 41 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 42 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |

Tab 1. Windows Vinyl Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|--|
| 43 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 44 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 45 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 46 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 47 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 48 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 49 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 50 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 51 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 52 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 53 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 54 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 55 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 56 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 57 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 58 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 59 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 60 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 61 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 62 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 63 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 64 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 65 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 66 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 67 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 68 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 69 | 1934 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 70 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 71 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 72 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 73 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 74 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 75 | 1934 | 2012 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 76 | 1934 | 2012 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 77 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 78 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 79 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 80 | 1931 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 81 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 82 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 83 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 84 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |

Tab 1. Windows Vinyl Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|--|
| 85 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 86 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 87 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 88 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 89 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 90 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 91 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 92 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 93 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 94 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 95 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 96 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 97 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 98 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 99 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 100 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 101 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 102 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 103 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 104 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 105 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 106 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 107 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 108 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 109 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 110 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 111 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 112 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 113 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 114 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 115 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 116 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 117 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 118 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 119 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 120 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 121 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 122 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 123 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 124 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 125 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 126 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |

Tab 1. Windows Vinyl Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|--|
| 127 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 128 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 129 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 130 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 131 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 132 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 133 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 134 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 135 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 136 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 137 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 138 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 139 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 140 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 141 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 142 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 143 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 144 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 145 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 146 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 147 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 148 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 149 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 150 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 151 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 152 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 153 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 154 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 155 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 156 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 157 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 158 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 159 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 160 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 161 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 162 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 163 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 164 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 165 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 166 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 167 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 168 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |

Tab 1. Windows Vinyl Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|--|
| 169 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 170 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 171 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 172 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 173 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 174 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 175 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 176 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 177 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 178 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 179 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 180 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 181 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 182 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 183 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 184 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 185 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 186 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 187 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 188 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 189 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 190 | 1923 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 191 | 1923 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 192 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 193 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 194 | 1923 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 195 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 196 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 197 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 198 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 199 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 200 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 201 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 202 | 1923 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |

Tab 2. PVC Window Trim

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|---|
| 1 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 2 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 3 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 4 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 5 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 6 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 7 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 8 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 9 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 10 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 11 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 12 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 13 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 14 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 15 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 16 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 17 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 18 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 19 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 20 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 21 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty on the frames |
| 22 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 23 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 24 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 25 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 26 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 27 | 1934 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 28 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 29 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 30 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 31 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 32 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 33 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 34 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 35 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 36 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 37 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 38 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 39 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 40 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 41 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 42 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |

Tab 2. PVC Window Trim

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|---|
| 43 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 44 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 45 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 46 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 47 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 48 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 49 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 50 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 51 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 52 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 53 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 54 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 55 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 56 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 57 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 58 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 59 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 60 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 61 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 62 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 63 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 64 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 65 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 66 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 67 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 68 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 69 | 1934 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 70 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 71 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 72 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 73 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 74 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 75 | 1934 | 2012 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 76 | 1934 | 2012 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 77 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 78 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 79 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 80 | 1931 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 81 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 82 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 83 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 84 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |

Tab 2. PVC Window Trim

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|---|
| 85 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 86 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 87 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 88 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 89 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 90 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 91 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 92 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 93 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 94 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 95 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 96 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 97 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 98 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 99 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 100 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 101 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 102 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 103 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 104 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 105 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 106 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 107 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 108 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 109 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 110 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 111 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 112 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 113 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 114 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 115 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 116 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 117 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 118 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 119 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 120 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 121 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 122 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 123 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 124 | 1934 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 125 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 126 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |

Tab 2. PVC Window Trim

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|---|
| 127 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 128 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 129 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 130 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 131 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 132 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 133 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 134 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 135 | 1934 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 136 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 137 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 138 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 139 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 140 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 141 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 142 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 143 | 1934 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 144 | 1934 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 145 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 146 | 1934 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 147 | 1934 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 148 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 149 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 150 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 151 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 152 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 153 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 154 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 155 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 156 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 157 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 158 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 159 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 160 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 161 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 162 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 163 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 164 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 165 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 166 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 167 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 168 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |

Tab 2. PVC Window Trim

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|---|
| 169 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 170 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 171 | 1931 | 2020 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 172 | 1931 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 173 | 1931 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 174 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 175 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 176 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 177 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 178 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 179 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 180 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 181 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 182 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 183 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 184 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 185 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 186 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 187 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 188 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 189 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 190 | 1923 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 191 | 1923 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 192 | 1923 | 2016 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 193 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 194 | 1923 | 2015 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 195 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 196 | 1923 | 2017 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 197 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 198 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 199 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 200 | 1923 | 2018 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 201 | 1923 | 2019 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |
| 202 | 1923 | 2014 | TBD | TBD | Y | Y | 40 | Material Lifetime warranty for orig owner |

Tab 3. Windows, In-kind Wood Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|-------------------------------|
| 1 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 2 | 1931 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 3 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 4 | 1931 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 5 | 1931 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 6 | 1931 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 7 | 1931 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 8 | 1931 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 9 | 1931 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 10 | 1931 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 11 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 12 | 1931 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 13 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 14 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 15 | 1931 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 16 | 1931 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 17 | 1931 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 18 | 1934 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 19 | 1930 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 20 | 1930 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 21 | 1930 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 22 | 1930 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 23 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 24 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 25 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 26 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 27 | 1930 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 28 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 29 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 30 | 1930 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 31 | 1930 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 32 | 1930 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 33 | 1930 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 34 | 1930 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 35 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 36 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 37 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 38 | 1939 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 39 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 40 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 41 | 1934 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 42 | 1934 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |

Tab 3. Windows, In-kind Wood Replacement

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|-------------------------------|
| 43 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 44 | 1934 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 45 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 46 | 1934 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 47 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 48 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 49 | 1934 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 50 | 1934 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 51 | 1935 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 52 | 1934 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 53 | 1935 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 54 | 1934 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 55 | 1935 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 56 | 1934 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 57 | 1935 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 58 | 1934 | 2015 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 59 | 1934 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 60 | 1935 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 61 | 1935 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 62 | 1935 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 63 | 1935 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 64 | 1935 | 2015 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 65 | 1935 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 66 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 67 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 68 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 69 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 70 | 1939 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 71 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 72 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 73 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 74 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 75 | 1939 | 2019 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 76 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 77 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 78 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 79 | 1939 | 2017 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 80 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 81 | 1939 | 2016 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 82 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |
| 83 | 1939 | 2018 | TBD | TBD | Y | Y | 20 | Defect replacement |

Tab 4. Synthetic Slate Roofing

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|-------------------------------|
| 1 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 2 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 3 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 4 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 5 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 6 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 7 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 8 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 9 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 10 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 11 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 12 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 13 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 14 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 15 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 16 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 17 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 18 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 19 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 20 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 21 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 22 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 23 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 24 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 25 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 26 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 27 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 28 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 29 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 30 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 31 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 32 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 33 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 34 | 1934 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 35 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 36 | 1934 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 37 | 1930 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 38 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 39 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 40 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 41 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 42 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |

Tab 4. Synthetic Slate Roofing

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|---|-----------------|--------------------------|-------------------------------|
| 43 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 44 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 45 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 46 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 47 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 48 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 49 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 50 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 51 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 52 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 53 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 54 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 55 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 56 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 57 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 58 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 59 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 60 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 61 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 62 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 63 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 64 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 65 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 66 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 67 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 68 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 69 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 70 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 71 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 72 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 73 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 74 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 75 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 76 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |

Tab 5. Fiber Cement Siding

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|-------------------------------|
| 1 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 2 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 3 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 4 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 5 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 6 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 7 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 8 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 9 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 10 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 11 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 12 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 13 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 14 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 15 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 16 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 17 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 18 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 19 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 20 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 21 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 22 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 23 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 24 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 25 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 26 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 27 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 28 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 29 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 30 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 31 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 32 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 33 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 34 | 1934 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 35 | 1931 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 36 | 1934 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 37 | 1930 | 2009 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 38 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 39 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 40 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 41 | 1934 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 42 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 43 | 1931 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |

Tab 5. Fiber Cement Siding

| Housing Unit Number | Date of Unit Construction | Year New Material Installed (initial installation) | Year New Material Replaced | Total Lifecycle of New Material | Lead Paint Hazard Removed? (Y/N/ Not Applicable) | Warranty? (Y/N) | Warranty Number of Years | Warranty Terms of Replacement |
|---------------------|---------------------------|--|----------------------------|---------------------------------|--|-----------------|--------------------------|-------------------------------|
| 44 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 45 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 46 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 47 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 48 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 49 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 50 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 51 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 52 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 53 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 54 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 55 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 56 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 57 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 58 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 59 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 60 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 61 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 62 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 63 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 64 | 1930 | 2010 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 65 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 66 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 67 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 68 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 69 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 70 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 71 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 72 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 73 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 74 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 75 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |
| 76 | 1939 | 2011 | TBD | TBD | Not Applicable | Y | 50 | Material replacement |