

**APPENDIX to the 2020 Annual Report for the Program Comment for
Department of the Army Inter-War Era Historic Housing, Associated Buildings and Structures, and Landscape Features (1919–1940)**

Lifecycle Data Tracking for Imitative Substitute Building Materials and In-kind Building Materials

This information is provided in accordance with the requirements of the Program Comment for Department of the Army Inter-War Era Historic Housing, Associated Buildings and Structures, and Landscape Features (1919–1940) (Program Comment) issued by the Advisory Council on Historic Preservation on 4 Sep 2020. These data represent Army tracking of lifecycle data for in-kind and imitative substitute building materials used on 361 Inter-War Era housing units present on two Army installations, one in the in mid-Atlantic (in-kind wood replacement windows, synthetic (faux) slate roofing, and fiber cement siding), and the other in the Southeast (vinyl replacement windows, PVC window trim). The Tabs on this spreadsheet correspond to the building materials type and contain the data points being tracked for each building material type. The data will be collected at the individual housing unit level and reported annually from 2020 to 2025, and will then be collected and reported at five-year intervals, in 2030, 2035, 2040, 2045, 2050, and 2055. These data are presented to the ACHP as part of the 2020 Annual Report and represent the initial submission of these data in satisfaction of the Program Comment.

361 total Inter-War Era historc housing units are being tracked. The following in-kind building material and imitative substitute building material types used on the 361 Inter-war Era historic housing units are tracked in the corresponding Tabs, in accordance with the Program Comment:

- Tab 1. Windows, vinyl replacement - 202 housing units
- Tab 2. PVC window trim - 202 housing units
- Tab 3. Windows, in-kind wood replacement - 83 housing units
- Tab 4. Synthetic slate roofing - 76 housing units
- Tab 5. Fiber cement siding - 76 housing units

The following data points are presented in each TAB for each in-kind building material and imitative substitute building material type. Data Columns E and F will be populated as materials are replaced:

- A. Housing Unit Number
- B. Date of Housing Unit Construction
- C. Year New Material Installed (initial installation)
- D. Year New Material Replaced - this information will be filled out as the material is replaced
- E. Total Lifecycle of New Material - lifecycle will be calculated at the time of replacement of new material (number of years)
- F. Lead Paint Hazard Removed? (Y/N/ Not Applicable)
- G. Warranty (y/n)
- H. Warranty (# years)
- I. Warranty Terms of Replacement - includes information regarding terms of replacement (if any)

To ensure accuracy, the Army will change, amend, update, or withdraw and correct these data at any time, as needed.

Tab 1. Windows Vinyl Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
1	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
2	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
3	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
4	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
5	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
6	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
7	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
8	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
9	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
10	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
11	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
12	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
13	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
14	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
15	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
16	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
17	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
18	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
19	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
20	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
21	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
22	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
23	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
24	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
25	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
26	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
27	1934	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
28	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
29	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
30	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
31	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
32	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
33	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
34	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
35	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
36	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
37	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
38	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
39	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
40	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
41	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
42	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames

Tab 1. Windows Vinyl Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
43	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
44	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
45	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
46	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
47	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
48	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
49	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
50	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
51	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
52	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
53	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
54	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
55	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
56	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
57	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
58	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
59	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
60	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
61	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
62	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
63	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
64	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
65	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
66	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
67	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
68	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
69	1934	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
70	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
71	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
72	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
73	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
74	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
75	1934	2012	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
76	1934	2012	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
77	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
78	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
79	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
80	1931	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
81	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
82	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
83	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
84	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames

Tab 1. Windows Vinyl Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
85	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
86	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
87	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
88	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
89	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
90	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
91	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
92	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
93	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
94	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
95	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
96	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
97	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
98	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
99	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
100	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
101	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
102	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
103	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
104	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
105	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
106	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
107	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
108	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
109	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
110	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
111	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
112	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
113	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
114	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
115	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
116	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
117	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
118	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
119	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
120	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
121	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
122	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
123	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
124	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
125	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
126	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames

Tab 1. Windows Vinyl Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
127	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
128	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
129	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
130	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
131	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
132	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
133	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
134	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
135	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
136	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
137	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
138	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
139	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
140	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
141	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
142	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
143	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
144	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
145	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
146	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
147	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
148	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
149	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
150	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
151	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
152	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
153	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
154	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
155	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
156	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
157	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
158	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
159	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
160	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
161	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
162	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
163	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
164	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
165	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
166	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
167	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
168	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames

Tab 1. Windows Vinyl Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
169	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
170	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
171	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
172	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
173	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
174	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
175	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
176	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
177	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
178	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
179	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
180	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
181	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
182	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
183	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
184	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
185	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
186	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
187	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
188	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
189	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
190	1923	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
191	1923	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
192	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
193	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
194	1923	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
195	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
196	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
197	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
198	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
199	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
200	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
201	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
202	1923	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames

Tab 2. PVC Window Trim

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
1	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
2	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
3	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
4	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
5	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
6	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
7	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
8	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
9	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
10	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
11	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
12	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
13	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
14	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
15	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
16	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
17	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
18	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
19	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
20	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
21	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty on the frames
22	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
23	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
24	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
25	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
26	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
27	1934	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
28	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
29	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
30	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
31	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
32	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
33	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
34	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
35	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
36	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
37	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
38	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
39	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
40	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
41	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
42	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner

Tab 2. PVC Window Trim

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
43	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
44	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
45	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
46	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
47	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
48	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
49	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
50	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
51	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
52	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
53	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
54	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
55	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
56	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
57	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
58	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
59	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
60	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
61	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
62	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
63	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
64	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
65	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
66	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
67	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
68	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
69	1934	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
70	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
71	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
72	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
73	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
74	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
75	1934	2012	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
76	1934	2012	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
77	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
78	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
79	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
80	1931	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
81	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
82	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
83	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
84	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner

Tab 2. PVC Window Trim

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
85	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
86	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
87	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
88	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
89	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
90	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
91	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
92	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
93	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
94	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
95	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
96	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
97	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
98	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
99	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
100	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
101	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
102	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
103	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
104	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
105	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
106	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
107	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
108	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
109	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
110	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
111	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
112	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
113	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
114	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
115	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
116	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
117	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
118	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
119	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
120	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
121	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
122	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
123	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
124	1934	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
125	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
126	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner

Tab 2. PVC Window Trim

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
127	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
128	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
129	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
130	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
131	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
132	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
133	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
134	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
135	1934	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
136	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
137	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
138	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
139	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
140	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
141	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
142	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
143	1934	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
144	1934	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
145	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
146	1934	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
147	1934	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
148	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
149	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
150	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
151	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
152	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
153	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
154	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
155	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
156	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
157	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
158	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
159	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
160	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
161	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
162	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
163	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
164	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
165	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
166	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
167	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
168	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner

Tab 2. PVC Window Trim

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
169	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
170	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
171	1931	2020	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
172	1931	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
173	1931	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
174	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
175	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
176	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
177	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
178	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
179	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
180	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
181	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
182	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
183	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
184	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
185	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
186	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
187	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
188	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
189	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
190	1923	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
191	1923	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
192	1923	2016	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
193	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
194	1923	2015	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
195	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
196	1923	2017	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
197	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
198	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
199	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
200	1923	2018	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
201	1923	2019	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner
202	1923	2014	TBD	TBD	Y	Y	40	Material Lifetime warranty for orig owner

Tab 3. Windows, In-kind Wood Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
1	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
2	1931	2018	TBD	TBD	Y	Y	20	Defect replacement
3	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
4	1931	2017	TBD	TBD	Y	Y	20	Defect replacement
5	1931	2017	TBD	TBD	Y	Y	20	Defect replacement
6	1931	2018	TBD	TBD	Y	Y	20	Defect replacement
7	1931	2018	TBD	TBD	Y	Y	20	Defect replacement
8	1931	2017	TBD	TBD	Y	Y	20	Defect replacement
9	1931	2018	TBD	TBD	Y	Y	20	Defect replacement
10	1931	2017	TBD	TBD	Y	Y	20	Defect replacement
11	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
12	1931	2019	TBD	TBD	Y	Y	20	Defect replacement
13	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
14	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
15	1931	2019	TBD	TBD	Y	Y	20	Defect replacement
16	1931	2017	TBD	TBD	Y	Y	20	Defect replacement
17	1931	2016	TBD	TBD	Y	Y	20	Defect replacement
18	1934	2017	TBD	TBD	Y	Y	20	Defect replacement
19	1930	2016	TBD	TBD	Y	Y	20	Defect replacement
20	1930	2017	TBD	TBD	Y	Y	20	Defect replacement
21	1930	2016	TBD	TBD	Y	Y	20	Defect replacement
22	1930	2016	TBD	TBD	Y	Y	20	Defect replacement
23	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
24	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
25	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
26	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
27	1930	2017	TBD	TBD	Y	Y	20	Defect replacement
28	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
29	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
30	1930	2019	TBD	TBD	Y	Y	20	Defect replacement
31	1930	2016	TBD	TBD	Y	Y	20	Defect replacement
32	1930	2018	TBD	TBD	Y	Y	20	Defect replacement
33	1930	2018	TBD	TBD	Y	Y	20	Defect replacement
34	1930	2018	TBD	TBD	Y	Y	20	Defect replacement
35	1939	2018	TBD	TBD	Y	Y	20	Defect replacement
36	1939	2018	TBD	TBD	Y	Y	20	Defect replacement
37	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
38	1939	2019	TBD	TBD	Y	Y	20	Defect replacement
39	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
40	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
41	1934	2016	TBD	TBD	Y	Y	20	Defect replacement
42	1934	2017	TBD	TBD	Y	Y	20	Defect replacement

Tab 3. Windows, In-kind Wood Replacement

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
43	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
44	1934	2017	TBD	TBD	Y	Y	20	Defect replacement
45	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
46	1934	2016	TBD	TBD	Y	Y	20	Defect replacement
47	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
48	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
49	1934	2016	TBD	TBD	Y	Y	20	Defect replacement
50	1934	2019	TBD	TBD	Y	Y	20	Defect replacement
51	1935	2017	TBD	TBD	Y	Y	20	Defect replacement
52	1934	2017	TBD	TBD	Y	Y	20	Defect replacement
53	1935	2018	TBD	TBD	Y	Y	20	Defect replacement
54	1934	2016	TBD	TBD	Y	Y	20	Defect replacement
55	1935	2019	TBD	TBD	Y	Y	20	Defect replacement
56	1934	2016	TBD	TBD	Y	Y	20	Defect replacement
57	1935	2019	TBD	TBD	Y	Y	20	Defect replacement
58	1934	2015	TBD	TBD	Y	Y	20	Defect replacement
59	1934	2018	TBD	TBD	Y	Y	20	Defect replacement
60	1935	2019	TBD	TBD	Y	Y	20	Defect replacement
61	1935	2017	TBD	TBD	Y	Y	20	Defect replacement
62	1935	2018	TBD	TBD	Y	Y	20	Defect replacement
63	1935	2016	TBD	TBD	Y	Y	20	Defect replacement
64	1935	2015	TBD	TBD	Y	Y	20	Defect replacement
65	1935	2018	TBD	TBD	Y	Y	20	Defect replacement
66	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
67	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
68	1939	2018	TBD	TBD	Y	Y	20	Defect replacement
69	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
70	1939	2019	TBD	TBD	Y	Y	20	Defect replacement
71	1939	2018	TBD	TBD	Y	Y	20	Defect replacement
72	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
73	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
74	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
75	1939	2019	TBD	TBD	Y	Y	20	Defect replacement
76	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
77	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
78	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
79	1939	2017	TBD	TBD	Y	Y	20	Defect replacement
80	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
81	1939	2016	TBD	TBD	Y	Y	20	Defect replacement
82	1939	2018	TBD	TBD	Y	Y	20	Defect replacement
83	1939	2018	TBD	TBD	Y	Y	20	Defect replacement

Tab 4. Synthetic Slate Roofing

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
1	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
2	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
3	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
4	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
5	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
6	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
7	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
8	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
9	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
10	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
11	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
12	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
13	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
14	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
15	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
16	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
17	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
18	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
19	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
20	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
21	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
22	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
23	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
24	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
25	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
26	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
27	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
28	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
29	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
30	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
31	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
32	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
33	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
34	1934	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
35	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
36	1934	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
37	1930	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
38	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
39	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
40	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
41	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
42	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement

Tab 4. Synthetic Slate Roofing

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
43	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
44	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
45	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
46	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
47	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
48	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
49	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
50	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
51	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
52	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
53	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
54	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
55	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
56	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
57	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
58	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
59	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
60	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
61	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
62	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
63	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
64	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
65	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
66	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
67	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
68	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
69	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
70	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
71	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
72	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
73	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
74	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
75	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
76	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement

Tab 5. Fiber Cement Siding

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
1	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
2	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
3	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
4	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
5	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
6	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
7	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
8	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
9	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
10	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
11	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
12	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
13	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
14	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
15	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
16	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
17	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
18	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
19	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
20	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
21	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
22	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
23	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
24	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
25	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
26	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
27	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
28	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
29	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
30	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
31	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
32	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
33	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
34	1934	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
35	1931	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
36	1934	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
37	1930	2009	TBD	TBD	Not Applicable	Y	50	Material replacement
38	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
39	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
40	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
41	1934	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
42	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
43	1931	2010	TBD	TBD	Not Applicable	Y	50	Material replacement

Tab 5. Fiber Cement Siding

Housing Unit Number	Date of Unit Construction	Year New Material Installed (initial installation)	Year New Material Replaced	Total Lifecycle of New Material	Lead Paint Hazard Removed? (Y/N/ Not Applicable)	Warranty? (Y/N)	Warranty Number of Years	Warranty Terms of Replacement
44	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
45	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
46	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
47	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
48	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
49	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
50	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
51	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
52	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
53	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
54	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
55	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
56	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
57	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
58	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
59	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
60	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
61	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
62	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
63	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
64	1930	2010	TBD	TBD	Not Applicable	Y	50	Material replacement
65	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
66	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
67	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
68	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
69	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
70	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
71	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
72	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
73	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
74	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
75	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement
76	1939	2011	TBD	TBD	Not Applicable	Y	50	Material replacement